

Field-level Assessment of Mg-rich Primer

John Stropki (Battelle) Jim Tankersley (Battelle)

Environment, Energy & Sustainability Symposium Denver, CO May 7, 2009

maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to ompleting and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding an DMB control number.	ion of information. Send comments arters Services, Directorate for Info	regarding this burden estimate or rmation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	nis collection of information, Highway, Suite 1204, Arlington		
1. REPORT DATE 07 MAY 2009		2. REPORT TYPE		3. DATES COVE 00-00-2009	red to 00-00-2009		
4. TITLE AND SUBTITLE		5a. CONTRACT NUMBER					
Field-level Assessm	nent of Mg-rich Prin	5b. GRANT NUMBER					
		5c. PROGRAM ELEMENT NUMBER					
6. AUTHOR(S)					5d. PROJECT NUMBER		
		5e. TASK NUMBER					
		5f. WORK UNIT NUMBER					
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Battelle,505 King Avenue,Columbus,OH,43201					8. PERFORMING ORGANIZATION REPORT NUMBER		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)					10. SPONSOR/MONITOR'S ACRONYM(S)		
				11. SPONSOR/M NUMBER(S)	ONITOR'S REPORT		
12. DISTRIBUTION/AVAIL Approved for publ	LABILITY STATEMENT ic release; distributi	on unlimited					
	OTES DIA Environment, I in Denver, CO. U.S.				um & Exhibition		
14. ABSTRACT							
15. SUBJECT TERMS							
16. SECURITY CLASSIFIC	ATION OF:		17. LIMITATION OF	18. NUMBER	19a. NAME OF		
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified	Same as Report (SAR)	OF PAGES 24	RESPONSIBLE PERSON		

Report Documentation Page

Form Approved OMB No. 0704-0188

Presentation Overview



- Project Team
- Objective and Purpose
- Technical Approach
- Results of Laboratory Testing
- Results of Field Testing
- Conclusions
- Planned Future Activities
- Questions



Project Team

- COTR Thomas J. Lorman, 77AESW (ASC/ENVV)
- Primary Project Stakeholders
 - Mike Spicer, AFRL/CTIO
 - Joel Johnson, AFRL
 - MSgt. Mike Ramsey, Florida Air National Guard
- Additional Stakeholders
 - AFRL/CTIO, F-22 SPO, F-35 SPO, FANG, Boeing, Akzo-Nobel Aerospace Coatings (ANAC), NAVAIR Pax River, Hill AFB, NASA - Kennedy Space Center
 - Battelle's Florida Materials Research Facility



Objective and Purpose

Objective

 Validate an environmentally friendly coating system through laboratory coupon tests and outdoor exposure tests on select non-chromate coating system stack-ups for use on legacy, as well as the F-22 and F-35 aircraft

Purpose

- Testing will serve to validate the chemical and physical performance requirements specified in T.O. 1-1-8 and other applicable T.Os referenced for approved Air Force coating systems
- Data gathered from this project will be provided to F-22 and F-35 SPO for possible application of the non-chromate stackup to metallic and composite structures

Battelle The Business of Innovation

Technical Approach

- Scope
 - Conduct controlled "round-robin" laboratory tests to assess performance of Prekote pretreatment, Mg-rich primer, and Aerodur 5000
- Deliverables

<u>Demonstration Test Plan</u>

- Integrate testing and analysis protocols with Boeing-Long Beach, AFRL/CTIO, Akzo-Nobel Aerospace Coatings, NAVAIR Pax River, Hill AFB, NASA Kennedy Space Center
- Test Plan included testing protocols, articles, substrate matrices, surface treatments, primers, and topcoats
- Test Plan complements Round Robin Test Plan drafted by UDRI and provided to Battelle May 2008

Technical Data Package

 Literature survey, technical review and reporting on components contained in non-chromate coating systems being investigated for project

BattelleThe Business of Innovation

Mg-rich Coating Formulations

- Prototype university formulation (2004)
 - Utilized 100+ mm Mg particles and five component resin system
 - Performance in B-117 and cyclic salt spray very good
- Akzo-Nobel Aerospace Coatings (ANAC) licenses technology (2004)
 - Worked to resolve surface roughness, compliance, and "usability" issues
- PD374-165 (2005)
 - First formulation with viable smaller Mg particle; utilization of a two component resin system
 - Performance in B-117 marginally good
- PD406-35 (2005)
 - Modification of resin system; VOC compliant using exempt solvents; performance in B-117 good
- XP405-110 (2006)
 - Optimized Mg pigment volume concentration (PVC)
 - Performance excellent over bare and PreKote panels, some adhesion loss over fresh Alodine 1200
 - Some samples prepared with an "active" lot of Mg powder; excess of fines created blistering
- XP417-183 (2007)
 - Resin system modified to improve flexibility and performance over Alodine 1200
 - Improved overall performance as reported by ANAC
- XP455-30 aka "Aerodur 2100" (2007-2008)
 - Inclusion of green pigment for contrast ratio; reported to have no adverse effect on performance



XP417-183 Most Reported Results Good


ANAC (2,000 hrs. B117)



AFRL (HH-60)



NAVAIR
5,000 hrs B117 AA2024-T3
Primer Only Topcoated





Technical Approach Phase I – Laboratory Assessment - Status


- ASTM B-117 Exposure Testing of Coated Test Panels
 - Required 3,000 hour or 125 day exposure period with visual assessments every 504 hours
 - ANAC and AFRL coated panels (Aerodur 2100)
 - First exposure test terminated after ~650 hours by AFRL/CTIO because of test protocol issues (i.e., X-scribe morphology and test environment)





Technical Approach Phase I – Laboratory Assessment - Status

- Must seriously address the issue of scribe morphology on potential performance in B-117 test environment
 - Growing body of evidence showing that "rough" scribes can have a serious impact on performance, even for Cr controls




ANAC generated scribe variability on Cr controls; same topcoated, Cr-primer system, four different scribe methods after 650 hours of B-117




Scribe Morphology (cont.)

- In nearly all cases, significant amounts of corrosion product is seen on the rough "conventional cut" side of the scribe and very little on the smooth "climb cut" side
- Reduced Chromate Control
 - PreKote / Deft 02-Y-40 / Deft 99-GY-001 (color 36173)



Sample 799-A1D-016 2024-T3 Bare



Sample 799-D1D-016 7075-T6 Bare

Battelle The Business of Innovation

Round Robin Results – 650 hours Chromated Controls


AFRL 896-AAC-C01 896-AAC-C03 896-AAC-C02 896-ACC-C03 896-ACC-C02 896-ACC-C01






Round Robin Results — 650 hours Mg-rich Primer (Aerodur 2100)

AFRL









Technical Approach Phase I – Field Assessment - Status

- Exposure Testing of Coated Test Panels
 - 12-month Exposure Tests
 - Commenced June 25, 2008 at FMRF
 - Commenced October 9, 2008 at FANG
 - Nine month FMRF exposure conducted on March 18, 2009
 - No significant change in scribe rating
 - Undercutting detected on select panel sets
 - Blistering on "blank" test panels (no primer)
 - No major chalking, gloss or color changes (ΔE<1)





Technical Approach Phase I – Field Assessment - Status



9-month Exposure Results
- no visual changes noted
(typical)



Technical Approach Phase I — Field Assessment (9-months)

Set ID	Panel ID	Surface Treatment	Primer	Topcoat	Scribe Corrosion	Undercutting	Blistering
A	ACU/ACC	MEK/Brulin GD815/Phos. Acid/1200 S	Deft 02-Y-04	Aerodur 5000	1/1	0/0	0/0
A	AAU/AAC	ANAC Std/1200 S	Deft 02-Y04	Aerodur 5000	1/1	1/1	0/0
В	BCU/BCC	Prekote	PRC 7233	PRC 9311	0/0	0/0	0/0
В	BAU/BAC	Prekote	PRC 7233	PRC 9311	0/0	0/0	0/0
С	CCU/CCC	Prekote	Blank	Aerodur 5000	2/2	4/4	1/0
С	CAU/CAC	Prekote	Blank	Aerodur 5000	2/2	4/4	0/1
D	DCU/DCC	Prekote	ANAC Mg 1	Aerodur 5000	2/1	1/0	1/0
D	DAU/DAC	Prekote	ANAC Mg 1	Aerodur 5000	2/2	2/3	1/0
Е	ECU/ECC	Prekote	ANAC Mg 2	Aerodur 5000	2/2	3/2	0/0
Е	EAU/EAC	Prekote	ANAC Mg 2	Aerodur 5000	2/2	1/0	0/0
F	FCU/FCC	Prekote	ANAC 2100	Aerodur 5000	2/2	0/1	0/0
F	FAU/FAC	Prekote	ANAC 2100	Aerodur 5000	2/1	1/0	0/0



Technical Approach Phase II – Field Assessment

 Test two non-chromate stack-ups on static A/C at Florida ANG (125th Fighter Wing), Jacksonville, FL



- Additional exposure testing of coated panels and sensors at FANG and FMRF for data correlation purposes
- Sections of a/c painted include: upper/lower wing, lower fuselage
- Coordination between ANG and AFRL/CTIO




Technical Approach Phase II – Field Assessment

- Stack-ups included:
 - PreKote/Aerodur 2100 primer/Aerodur 5000 topcoat
 - Alodine 5200/ANAC 577-630 primer/Aerodur 5000 topcoat
- Initial scuff-sand operations conducted during July 2008
- Weather-related delays (i.e., temperatures and rainfall) in completing application of primer and topcoat materials to test sections of all aircraft
- Decision was made by Battelle and FANG to postpone painting of aircraft until fall
- Final strip & painting of test sections and all surfaces of static aircraft completed October 10, 2008



F-102 Test Sections (2 of 4)





RH-side Fuselage

LH-side Upper Wing



F-106 Test Sections (2 of 4)




Primer #1 Primer #2

LH-side Fuselage

RH-side Lower Wing



T-33 Test Sections (2 of 4)



Primer 1
Primer 2

mer 2

RH-side Fuselage

RH-side Upper Wing



F-15 Primed and Topcoated



Primer Coated

Topcoat Completed



The "Crew"





Conclusions

- Initial laboratory testing of Mg-rich primer systems delayed as a result of scribing morphology and test environment compatibility with "novel" coating system
- ASTM B117 is not appropriate test method for Mg-rich primer
- 9-month outdoor exposure data confirms excellent performance of Prekote/PRC 7233/PRC 9311 and control systems. Aerodur 2100 primer performing well
- AFRL to determine next iteration of laboratory testing
- 2-year field exposure panel test results (Abbott), 6-18 month flight testing (H-60, P-3 and AH64A) of coated sensors (Abbott) and 9-month panels from subject project yield good results for Mg-rich primer stack-up
- NAVAIR results with Mg-rich primer are very encouraging
- Next generation of Mg-rich primer coating performance better than all previous generations
- Future need to address alternative polymeric backbone chemistries (i.e., flexible primers and multiple stack-up combinations)



Planned Future Activities

- Continued quarterly monitoring of field exposure test panels (FMRF and FANG)
- Preparation for next 3,000-hour laboratory test exposure
- Obtain color/gloss/chalk and corrosion assessments from four static aircraft